

Initial quick test log

Model series/Model designation	163.113	Workshop ID	
VIN	WDC1631131A339280	Steering	LEFT
Total distance driven		Version	7.7.3/09/2020 (2020-07-29)
Battery voltage	14.06 V		

VG - Transfer case				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
1635457932	39.2001	39.2001	0/03	12

ETC - Electronic transmission control				- F - i
MB number	HW version	SW version	Diagnosis version	Pin
0305452632	03.2001	14.2001	2/0	11
Code	Text		Status	
P2602	The voltage supply of the valves is faulty.		STORED	
P2502	The gear is implausible or the transmission is slipping.		STORED	
P2203	The internal electrical check of component Y3/6n3 (speed sensor 3) has failed.		Current and stored	
P220A	The speed comparison of Y3/6n2 to Y3/6n3 is implausible.		STORED	
Event	Text		Status	
P2600	The voltage supply of circuit 87 has undervoltage.		Event STORED	
P2316	One or more messages from control unit N19 (Air conditioning control module) are not available on the CAN bus. (CAN timeout fault)		Event STORED	

ESM - Electronic selector module				- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin
1635458432	27.2000	06.1999	0/08	9

CDI - Common Rail Diesel Injection				- F -
MB number	HW version	SW version	Diagnosis version	Pin
6121533279	14.2000	08.2001	0/5	7
Code	Text		Status	
P1481-016	Glow plug failure Cylinder 5		Current and stored	
P1630-016	Drive authorization Control unit Drive authorization does not answer		STORED	
P1192-004	B40 (Oil sensor (oil level, temperature and quality)) Short circuit / Open circuit		STORED	
P1192-032	B40 (Oil sensor (oil level, temperature and quality)) Oil level is implausible.		STORED	
P1403-032	Exhaust gas recirculation Negative control variation [Exhaust gas recirculation rate is too low.]		Current and stored	

ESP - Electronic stability program				- f -
MB number	HW version	SW version	Diagnosis version	Pin

1635458032	44.2000	44.2000	2/05	9
Code	Text			Status
C1022	Fault in CAN communication with control unit N3/10 (ME-SFI [ME] control unit).			STORED
C1140-007	N49 (Steering angle sensor)			STORED
C1140-008	Component N49 (Steering angle sensor) is not initialized.			STORED

BAS - Brake assist					- f -
MB number	HW version	SW version	Diagnosis version	Pin	
1635458032	40.1998	03.2000	0/03	9	
Code	Text			Status	
C1025-004	CAN communication with the engine control module is faulty. If no customer complaint exists, the fault can be erased.			STORED	

AB - Airbag					- F -
MB number	HW version	SW version	Diagnosis version	Pin	
1635422218	03.2001	09.2001	4/02	13	
Code	Text			Status	
B1315-016	Component B48 (Front passenger seat occupied and child seat recognition) is defective.			Current and stored	

AAM - All Activity Module					- f -
MB number	HW version	SW version	Diagnosis version	Pin	
1635457032	08.2001	33.2001	0/16	12	
Code	Text			Status	
B1040-008	CAN bus: fault in communication : Control unit Air conditioning			STORED	
B1040-005	CAN bus: fault in communication : N10/1 (Extended activity module (EAM))			STORED	
B1040-001	CAN bus: fault in communication : ESP / ETS If there is no malfunction, ignore the fault code.			STORED	
B1341	Communication fault with component H3/1 (Alarm signal siren with additional battery)			STORED	
B1858-002	Two-way radio signal : The programmed code is o.k., but the programmable code is not synchronized.			STORED	

EAM - Extended activity module					- f -
MB number	HW version	SW version	Diagnosis version	Pin	
1635457332	30.2001	50.2000	0/10	12	
Code	Text			Status	
B1041	CAN bus: fault in communication : ESP / ETS			STORED	
B1086	CAN bus: fault in communication : AAM			STORED	
B1040	CAN bus: fault in communication : Engine control module			STORED	
B1089	CAN bus: fault in communication : A55 (Transfer case (VG) range selection motor)			STORED	
B1088	CAN bus: fault in communication : A1 (Instrument cluster)			STORED	

DAS - Drive authorization system					- ✓ -
MB number	HW version	SW version	Diagnosis version	Pin	
1635452832	28.1999	24.2000	0/07	15	

LCP - Lower operating panel with power window function				- F -
MB number	HW version	SW version	Diagnosis version	Pin
1638205010	20.2001	31.2001	0/00	9
Code	Text			Status
B1213-008	Exterior rearview mirrors Left : The voltage supply of the setting potentiometer is faulty. The 'vertical adjustment' signal is faulty. Code 'Mirror memory fitted' is probably wrong. If there are no faults or complaints, the fault code can then be disregarded.			Current and stored
B1213-009	Exterior rearview mirrors Left : The voltage supply of the setting potentiometer is faulty. The 'horizontal adjustment' signal is faulty. Code 'Mirror memory fitted' is probably wrong. If there are no faults or complaints, the fault code can then be disregarded.			Current and stored
B1099	Fault in communication with component N72/2 (RCP control module).			STORED

ICM - Instrument cluster with maintenance interval display				- f -
MB number	HW version	SW version	Diagnosis version	Pin
1635404011	27.2001	51.2000	3/06	15
Code	Text			Status
B1040	Fault in CAN communication with control unit MR engine control.			STORED
B1042	Fault in CAN communication with control unit BAS Brake assist.			STORED

AAC - Automatic air conditioning				- F -
MB number	HW version	SW version	Diagnosis version	Pin
1638202589	34.2001	31.2001	128/8	12
Code	Text			Status
B1002	B10/6 (Evaporator temperature sensor)			STORED
B1003	B12/2 (Refrigerant pressure and temperature sensor)			STORED
B1004	B12/2 (Refrigerant pressure and temperature sensor)			STORED
B1005	B10/24 (Center vent outlet air temperature sensor)			STORED
B1006	B10/25 (Front footwell outlet air temperature sensor)			STORED
B1007	B10/7 (Rear outlet air temperature sensor)			STORED
B1008	B32 (Sun sensor)			STORED
B100A	M2/1 (Rear blower motor)			STORED
B1105	A9 (AC compressor)			STORED
B1201	M2/6 (Blended air flap positioning motor)			STORED
B1202	M2/22 (Center vent flap positioning motor)			STORED
B1203	M2/15 (Footwell flap positioning motor)			STORED
B1204	M2/8 (Defroster flap positioning motor)			STORED
B1205	M2/5 (Fresh and recirculated air flaps actuator)			STORED
B1206	M2/12 (Rear shutoff flap positioning motor)			Current and stored
B1207	M2/12 (Rear shutoff flap positioning motor)			STORED
B1208	A32n1 (Blower regulator)			STORED
B1302	Fault in CAN communication with control unit Lower control panel.			STORED
B1306	Fault in CAN communication with control unit N30/4 (ESP control module).			STORED